

Repair Parts For Use With V-9502 Pneumatic Valve Actuator Positioner


Description

The V-9502 Pneumatic valve positioners can be reconditioned using the parts from the selection chart below.

Selection Chart

Repair Parts For Use With V-9502 Pneumatic Valve Actuator Positioner

Code Number	Callout	Description
C-9506-1	A	Positioner Movement Complete Less Items "B" and "C"
D-9502-604	B	Operating Span Lever Arm Assembly
Refer to V-9502 Series Pneumatic Valve Actuator Positioners Catalog Page (LIT-1924100) on Page 84.	C	Springs



Repair Parts, V-9502